



Mounting Options for Magnehelic gauge

Models Select Chart

| Model | Description |
|-------|---|
| A-288 | "L" type metal mounting bracket with screws. |
| A-289 | "S" type metal mounting bracket with screws. |
| A-298 | Flat aluminum bracket for flush mounting Photohelic® & Capsuhelic® gages, 603A, 605, and 3000MR. |
| A-299 | Mounting bracket flush mount Magnehelic® gage in bracket. Bracket is then surface mounted . Steel with gray hammertone epoxy finish. 6.3" x 7.7" x 4.0", 1.30 lb. |
| A-300 | Flat aluminum bracket for flush mounting Magnehelic® gage. 6.8" x 6.0" x .1", .35 lb. |
| A-351 | Pinch clamp to seal rubber tubing, as in a leakage test. |
| A-352 | Magneclip, slip on magnetic holder for acrylic plastic gage, per pair. |
| A-353 | Magnetic mounting, flat style, secures to flowmeter, etc. with no. 6-32 machine screw and boots insert. |
| A-354 | Magnetic mounting, edge style, secures edge of acrylic manometer with No. 10-32 machine screw and boots insert. |
| A-356 | Gage plug with retainer loop, polyethylene plastic, for 1/4" ID tubing, slip loop over tubing OD and insert plug for seal. |
| A-357 | Thermometer and terminal tube holder, stainless steel wire. |
| A-360 | Aluminum DIN rail |
| A-362 | Stand-hang bracket, aluminum, for Minihelic® II gage. |
| A-363 | Scale clamp bar for 1221 manometer. |

| | |
|-------|---|
| A-364 | Magnet assembly for 1222 manometers, 2 required (3 required for 1222-36 and M-1000). |
| A-366 | Manometer cleaning brush, 1/4" OD x 2-1/8" long, attach to wire for use. |
| A-368 | Surface mounting plate, aluminum, for Magnehelic® gage. |
| A-369 | Stand-hang bracket, aluminum, for Magnehelic® gage. |
| A-370 | Flush mount bracket used with: Photohelic® 3000MR/MRS, Capsuhelic®, 631B Transmitter, EDA. Bracket is then surface mounted. Steel with gray hammertone epoxy finish. |
| A-371 | Surface mounting bracket, use with Photohelic® switch/gage on horizontal or vertical surfaces, also for Capsu-Photohelic® switch/gage on vertical only. Also Magnehelic® -MP, -HP models. |
| A-395 | Surface mounting bracket Series 4000 Capsuhelic® gages, steel with gray hammertone epoxy finish. |
| A-397 | Rugged step drill, quickly provides true round holes in thin materials, no center punch needed to start, automatically deburrs drilled hole, high speed steel, drills 3/16" through 1/2" holes in 1/16" increments. |
| A-464 | Flush mount kit for Magnehelic® gages. |
| A-465 | Flush mount space pressure sensor |
| A-497 | Mounting bracket for the Series 2-5000 Minihelic® II Differential Pressure Gage |