



Tachometer non contact type

Specification:-		
Measurement	:	10 to 99,999 RPM
Range Selection	:	10 to 99 RPM, 100 to 999 RPM, 1000 to 9999 RPM, 10000 to 99999 RPM
Best Accuracy	:	0.04% \pm 2dgt
Display	:	99999 counts
Target Distance	:	50mm to 200mm
Start/Hold	:	Start and Stop Measurement, Data Hold
Max/Min/Ave/Zero	:	Max. value, Min. value, Ave. Value, Zeroing
Sleep Mode	:	Around 15 minutes
Low Battery Display	:	Yes
Product Supply	:	Tachometer Unit, Batteries, Reflecting Tape, Manual